

2018 ROTARY-WING CAPABILITIES

For Pricing Contact:
repairstation@lord.com

OEM P/N	LORD P/N	PART DESCRIPTION	CONDITION TYPE	
BELL 204, 205, 212				
204-031-920-003	J-9797-6	Pylon Friction Damper Assembly	Overhaul Exchange	
204-031-920-003	J-16656-1	Pylon Friction Damper Assembly Repair Kit	New-PMA	
204-031-920-003	J-9993-3	Boot For Pylon Friction Damper Assy	New-PMA	
204-031-920-003	J-9994-1	Housing for Damper Assy	New-PMA	
204-031-920-003	Y-16960-3-1	Inner Member for Damper Assy	New-PMA	
204-031-927-005	J-8085-6	Mount Assy	Overhaul Exchange	
204-031-927-007	J-8085-8	Mount Assy	Overhaul Exchange	
212-030-273-001	J-14105-1	Cap Landing Gear Assy, Forward	Overhaul Exchange	
212-030-274-001	J-14106-1	Cap Landing Gear Assy, Aft	Overhaul Exchange	
212-030-436-007	J-15452-3	Landing Gear Strap	Overhaul Exchange	
212-030-437-007	J-15452-4	Landing Gear Strap	Overhaul Exchange	
BELL 206				
206-011-139-001	J-14258-3	Arm Assy (Flap Restraint)	Overhaul Exchange	
206-030-539-101	LB9-1301-1-1	Mount Assy (Pylon)	Overhaul Exchange	
206-033-501-001	LB1-1010-4-1	Support Assy (Forward)	Overhaul Exchange	
206-033-501-003	LB1-1010-6-1	Support Assy, LH	Overhaul Superseded by 206-033-501-101	
206-033-501-004	LB1-1010-6-2	Support Assy, RH	Overhaul Superseded by 206-033-501-102	
206-033-501-101	LB1-1010-22-1	Support Assy, LH	Overhaul Exchange	
206-033-501-102	LB1-1010-22-2	Support Assy, RH	Overhaul Exchange	
206-033-506-101	J-15413-17	Restraint, Transmission	Upgradable to 206-033-506-107	
206-033-506-107	J-15413-20	Restraint, Transmission	Overhaul Exchange	
206-033-506-107	J-15413-20	Restraint, Transmission	Repair	
206-033-506-109	J-15413-21	Restraint, Transmission	Overhaul Exchange	
206-033-506-109	J-15413-21	Restraint, Transmission	Repair	
206-033-516-101	LB9-1010-1-2	Flexure Assy, Nodal Beam	Overhaul Exchange	
206-033-518-005	J-15424-2	Stop Assy (Upstop)	Overhaul Exchange	
206-033-518-007	J-15425-2	Stop Assy (Downstop)	Overhaul Exchange	
206-033-544-001	LB9-1010-8-1	Support Assy, Isolation	Overhaul	
New Offering	206-033-545-001	LB9-1010-7-1	Elastomeric Bearing for 206-033-544-001	New-PMA
	206-033-554-101	LB6-1010-16-1	Link Assy (Pylon)	Overhaul Exchange
Now EASA Approved	206-310-004-101	LORD206-310-004101	Tension Torsion (TT) Strap	New-PMA(STC)
Now EASA Approved	206-310-004-103	LORD206-310-004103	Tension Torsion (TT) Strap	New-PMA(STC)
Now EASA Approved	Replaces: one 206-011-812-005, two B-2012, two 53642-75, two 206-411-814-003, two 206-011-862-001	LB2-1010-20-1	Elastomeric TR Trunnion Kit	New-PMA(STC)
Now EASA Approved	Replaces: one 206-011-812-005, two B-2012, two 53642-75, two 206-411-814-003, two 206-011-862-001	LB2-1010-20-2	Elastomeric TR Trunnion Bearing	New-PMA(STC)
	407-312-100-101	LB2-1232-1-1	Bearing, Flapping - Tail Rotor	Overhaul Exchange
BELL 214				
214-010-158-001	LB1-1003-1-1	Bearing Assy, Flapping	Overhaul Exchange	
214-030-614-003	LB9-1004-15-3	Torsion Arm Assy, Pylon Support, LH	Overhaul Exchange	
214-030-614-004	LB9-1004-15-4	Torsion Arm Assy, Pylon Support, RH	Overhaul Exchange	
214-030-615-003	LB9-1004-3-3	Clevis Assy, Pylon Support, LH	Overhaul Exchange	
214-030-615-004	LB9-1004-3-4	Clevis Assy, Pylon Support, RH	Overhaul Exchange	
214-031-612-115	J-17746-5	Spring, Elastomeric, Fwd and Aft	Overhaul Exchange	
214-031-614-105	LB9-1004-29-7	Arm Assy, LH	Overhaul Exchange	

2018 ROTARY-WING CAPABILITIES

For Pricing Contact:
repairstation@lord.com

	OEM P/N	LORD P/N	PART DESCRIPTION	CONDITION TYPE
BELL 214				
	214-031-614-107	J-16644-5	Plate Assy	Overhaul Exchange
	214-031-614-108	J-16644-6	Plate Assy	Overhaul Exchange
	214-031-614-125	LB9-1004-29-14	Arm Assy, RH	Overhaul Exchange
	214-031-614-127	J-16644-17	Plate Assy	Overhaul Exchange
	214-031-614-128	J-16644-18	Plate Assy	Overhaul Exchange
	214-031-615-105	LB9-1004-20-9	Clevis Assy, LH	Overhaul Exchange
	214-031-615-106	LB9-1004-20-10	Clevis Assy, RH	Overhaul Exchange
	214-031-617-113	LB9-1004-45-1	Spring	Overhaul Exchange
BELL 222 / 230				
	222-031-605-109	LB9-1302-5-1	Flex Assy	Overhaul
	222-331-617-103	LB1-1302-4-2	Isolation Mount, Lateral	Overhaul Exchange
	222-331-618-105	LB1-1302-3-1	Isolation Mount, Longitudinal	Overhaul Exchange
BELL 407				
New Offering	407-010-100 Series	REP-407-010-100 Series	Main Rotor Hub	Overhaul
	407-310-100-105	J-17750-24	Main Rotor Hub Damper	Overhaul Exchange
	407-310-100-107	J-17750-25	Main Rotor Hub Damper (Blue Coat)	Overhaul Exchange
SPEIIA-equipped part	407-310-101-101	LB9-1232-4-1	Shear Bearing	Overhaul Exchange
SPEIIA-equipped part	407-310-101-105	LB9-1232-6-1	Shear Bearing (Blue Coat)	Overhaul Exchange
SPEIIA-equipped part	407-310-102-101	LB4-1232-3-1	Lead Lag Bearing	Overhaul Exchange
SPEIIA-equipped part	407-310-102-103	LB4-1232-7-1	Lead Lag Bearing (Blue Coat)	Overhaul Exchange
	407-310-203-101	LB1-1232-5-1	Corner Mount	Overhaul Exchange
	407-312-100-101	LB2-1232-1-1	Tail Rotor Flapping Bearing	Overhaul Exchange
BELL 412				
	204-031-920-003	J-9797-6	Pylon Friction Damper Assembly	Overhaul Exchange
	204-031-920-003 (Repair Kit)	J-16656-1	Pylon Friction Damper Assembly Repair Kit	New-PMA
	204-031-920-003	J-9993-3	Boot For Pylon Friction Damper Assy	New-PMA
	204-031-920-003	J-9994-1	Housing for Damper Assy	New-PMA
	204-031-920-003	Y-16960-3-1	Inner Member for Damper Assy	New-PMA
	204-031-927-107	J-8085-50	Mount Assy	Overhaul Exchange
	212-030-436-007	J-15452-3	Landing Gear Strap	Overhaul Exchange
New Offering	412-010-100 Series	REP-412-010-100 Series	Main Rotor Hub	Overhaul
SPEIIA-equipped part	412-010-106-101	REP412-010-106-101	Bonded Pivot Bearing	Repair Exchange
Upgrade Available ▲	412-010-145-105	J-16663-4	Damper Yoke Set (Qty 4) ▽▽	Overhaul Exchange
	412-310-146-103	J-16663-7	Damper Yoke Set (Qty 4)	Overhaul Exchange
SPEIIA-equipped part	412-010-190-103	LB9-1062-8-2N	Spindle Bearing Assembly ▽ ▽	Overhaul
SPEIIA-equipped part	412-010-190-103	REPLB9-1062-8-2N	Spindle Bearing Assembly ▽ ▽	Repair
SPEIIA-equipped part	412-010-190-105	LB9-1062-18-1N	Spindle Bearing Assembly ▽ ▽	Overhaul
SPEIIA-equipped part	412-010-190-105	REPLB9-1062-18-1N	Spindle Bearing Assembly ▽ ▽	Repair
	412-030-437-103	J-16883-2	Aft Landing Gear Cap Assy	Overhaul Exchange
	412-330-437-101	J-16883-9	Aft Landing Gear Cap Assy	Overhaul Exchange
Upgrade Available ▲	412-330-437-103	J-23381-5	Rubber Bumper ▽▽▽	Overhaul Exchange
Fluid Resistant	412-330-437-107	J-23381-7	Rubber Bumper (New Design)	Overhaul Exchange
Fluid Resistant	412-330-437-105	J-16883-10	Aft Landing Gear Cap Assembly (New Design)	Overhaul Exchange
Fluid Resistant	412-340-102-101	412-340-102-101	Main Driveshaft Transmission Boot	New-PMA
Fluid Resistant	412-340-102-101	REP412-340-102-101	Main Driveshaft Transmission Boot	Overhaul Exchange

2018 ROTARY-WING CAPABILITIES

For Pricing Contact:
repairstation@lord.com

	OEM P/N	LORD P/N	PART DESCRIPTION	CONDITION TYPE
BELL 427				
	407-310-100-107	J-17750-25	Main Rotor Hub Damper (Blue Coat)	Overhaul Exchange
	407-310-101-107	LB9-1232-6-2	Shear Bearing	Overhaul Exchange
SPEIIA-equipped part	407-310-102-101	LB4-1232-3-1	Lead Lag Bearing	Overhaul Exchange
	407-310-102-103	LB4-1232-7-1	Lead Lag Bearing (Blue Coat)	Overhaul Exchange
	407-312-100-101	LB2-1232-1-1	Tail Rotor Flapping Bearing	Overhaul Exchange
	427-310-201-103	FL-1044-3	LIVE Mount	Overhaul Exchange
BELL 429				
	427-310-201-107	FL-1087-4	LIVE Mount	Overhaul Exchange
Upgrade Available ▲	429-310-001-105	J-23813-2	Lead-Lag Damper	Overhaul Exchange
	429-310-001-109	J-23813-4	Lead-Lag Damper	Overhaul Exchange
Upgrade Available ▲	429-310-003-101	LB4-1274-4-1	CF Bearing (Blue Coat)	Overhaul Exchange
	429-310-003-103	LB4-1274-5-1	CF Bearing (Blue Coat)	Overhaul Exchange
	429-310-201-105	J-23823-12	Pitch Restraint Spring Assembly	Overhaul Exchange
BELL 430				
	430-310-101-107	LB9-1220-2-5	Shear Restraint ▼	Exchange
	430-310-101-107	LB9-1220-2-5	Shear Restraint ▼	Overhaul
	430-310-104-105	FL-1030-8	Damper, Blade Set (Qty 2)	Rebuild Exchange
	430-310-200-107	FL-1027-7	Fluid Mount ▼	Overhaul
MD 500 / 520				
	369A1724-7	LB2-1056-17-1	Bearing (Tail Rotor Teetering)	New-PMA
	369D21400-503	J-15640-6	Main Rotor Damper	New-PMA
	369D21721-21	369D21721-21	Fork Assy (Tail Rotor)	Overhaul
SCHWEIZER 300 / 330				
	269A1290-003	J-15640-14	Main Rotor Blade Damper Assembly	New-PMA
	269A5667-003 Replaces: -005	LB2-1222-2-1	Tail Rotor Elastomeric Teeter Bearing	New-PMA

- ▼ Life-limited part. Historical Record Card required for overhaul/repair.
- ▼ LORD can upgrade the LB9-1062-8-2N (412-010-190-103) to the LB9-1062-18-1N (412-010-190-105)
- ▼▼ LORD can upgrade the J-16663-4 (412-010-145-105) to the J-16663-7 (412-310-146-103)
- ▼▼▼ LORD can upgrade the J-23381-5 (412-330-437-103) to the J-23381-7 (412-330-437-107)

All sales subject to LORD Terms and Conditions. Prices subject to change.

LORD is a trademark of LORD Corporation or one of its subsidiaries.

LORD provides valuable expertise in adhesives and coatings, vibration and motion control, and magnetically responsive technologies. Our people work in collaboration with our customers to help them increase the value of their products. Innovative and responsive in an ever-changing marketplace, we are focused on providing solutions for our customers worldwide.

LORD Corporation
World Headquarters
 111 Lord Drive
 Cary, NC 27511-7923
 USA

Parts handled directly by LORD
may be shipped DDP to:
 LORD Corporation
 Attn: Repair Station
 2455 Robison Road West
 Erie, PA 16509 USA
repairstation@lord.com

Customer Support Center (in United States & Canada)
 +1 877 ASK LORD (275 5673)
www.lord.com/mro
 Email: customer.support@lord.com; repairstation@lord.com
 For a listing of our worldwide locations, visit LORD.com.

